

MINNESOTA STREETCAR MUSEUM
OPERATIONS DEPARTMENT

OPERATIONS AND SAFETY BULLETIN
NUMBER 24C - 1

EFFECTIVE DATE: MAY 11, 2024

CANCELLATION DATE: IN EFFECT UNTIL RESCINDED

SUBJECT: SLOW SPEED THROUGH NORTH SIDING SWITCH

**TO: Foremen and Operators, Como-Harriet Streetcar
Line**

The switch stand at the north siding has been damaged. Although repairs have been made to allow the switch to operate, until further notice approach to and movement through the switch requires the following:

Heading south

1. Visual confirmation of the proper alignment of the switch to the main
2. Speed through the switch must be at a dead slow speed.

Heading north

1. Speed through the switch must be at dead slow speed.

BRUCE GUSTAFSON
General Superintendent