

MINNESOTA STREETCAR MUSEUM
TRANSPORTATION DEPARTMENT
Excelsior Streetcar Line

OPERATIONS AND SAFETY BULLETIN
NUMBER 18E - 3

EFFECTIVE DATE: SEPTEMBER 20, 2018

CANCELLATION DATE: IN EFFECT UNTIL RESCINDED

SUBJECT: OPERATION OF CAR No. 1239

TO: Foremen and Operators, Excelsior Streetcar Line

1. When operating car No. 1239 use extreme caution when moving around the front Motorman's compartment and the battery box on the floor. Given the proximity of the upper switch box, it is possible to hit your head on the switch box. When making movements around the battery box pay attention to the location of the switch box at all times.
2. When releasing the brakes on No. 1239, Operators must wait until all the air is exhausted before applying power. Not doing so results in undue strain on the motors and the brake shoes and associated rigging.

BRUCE GUSTAFSON
General Superintendent